


# Uptime® Elements



A visual framework detailing the steps necessary to establish a precision lubrication program.

1. Select the right lubricant
2. Apply the lubricant in the right amount at the right time
3. Keep the lubricant clean and dry
4. Keep the lubricant cool
5. Inspect, sample and analyze to ensure machine and lubricant health

**COLOR KEY**

- LUBRICATING OILS
- LUBRICATING GREASES
- BOTH OILS & GREASES

## Lubrication Leader™ Framework

© Copyright 2018-2024, Reliabilityweb.com. All rights reserved. No part of this graphic may be reproduced or transmitted in any form or by any means without the prior express written consent of Reliabilityweb.com. Reliabilityweb.com® and Uptime® are registered trademarks of Reliabilityweb.com in the U.S.A. and several other countries. Des-Case® is a registered trademark of Des-Case Cooperation.